

Current Sensor 5A/5mA

Model:TA12




Description:

Very small size, fully enclosed, circuit board welded, leading wiretype.

Purpose:

- Tele monitoring for electric load.
- As input signal to electric control system.
- Out of phase indication, electric quantity measure.
- Status monitoring for motor running.

Outline diagram: (dimensions in mm)



Specifications:

Output current	0-5mA
Sampling resistance	200 Ω
Sampling voltage	1V
Non-linearity	$\leq 0.3\%$
Phase shift	$\leq 10'$

Made in China