

WIFI CARD APPLE A1278 2008-2010 Model:607-4144-A



Description:

This is a replacement parts of Apple US AirPort Extreme Card for the MacBook Unibody A1278 A1286 A1297. Note this is a replacement part only, also an original part. If your MacBook Unibody built-in wireless does not work properly, you may need this replaced to solve such issues.

Specifications:

Product Name	WiFi Airport Card
Compatible Model	MacBook / Pro 13" A1278 2008 2009 2010 MacBook Pro 15" A1286 2008 2009 MacBook Pro 17" A1297 2009
Compatible Subfamily	A1278 MacBook "Core 2 Duo" 2.0 13" (Unibody) MacBook "Core 2 Duo" 2.4 13" (Unibody) MacBook Pro "Core 2 Duo" 2.26 13" (SD/FW) (09) MacBook Pro "Core 2 Duo" 2.53 13" (SD/FW) (09) MacBook Pro "Core 2 Duo" 2.4 13" Mid-2010 MacBook Pro "Core 2 Duo" 2.66 13" Mid-2010 A1286 MacBook Pro "Core 2 Duo" 2.4 15" (08) MacBook Pro "Core 2 Duo" 2.53 15" (08) MacBook Pro "Core 2 Duo" 2.8 15" (09) MacBook Pro "Core 2 Duo" 2.66 15" (SD)(09) MacBook Pro "Core 2 Duo" 2.66 15" (SD)(09) MacBook Pro "Core 2 Duo" 2.8 15" (SD)(09) MacBook Pro "Core 2 Duo" 2.8 15" (SD)(09) MacBook Pro "Core 2 Duo" 2.8 15" (SD)(09) MacBook Pro "Core 2 Duo" 2.93 15" (O9) MacBook Pro "Core 2 Duo" 2.93 15" (O9) MacBook Pro "Core 2 Duo" 3.06 15" (SD)(09)

	MacBook Pro "Core 2 Duo" 2.66 17" (09) MacBook Pro "Core 2 Duo" 2.8 17" Mid-2009 MacBook Pro "Core 2 Duo" 2.93 17" (09) MacBook Pro "Core 2 Duo" 3.06 17" Mid-2009
Compatible Model No	MB466LL/A, MB467LL/A, MB467LL/A, MB991LL/A, MC374LL/A, MC375LL/A, MB470LL/A, MB471LL/A, MC118LL/A, MC026LL/A, MB985LL/A, MB98 6LL/A, MB604LL/A, MC226LL/A*,

Made in China